

**NORTH EASTERN ELECTRICITY SUPPLY COMPANY OF ORISSA**  
**LIMITED OFFICE OF THE CHIEF EXECUTIVE OFFICER**

**Corporate Office:** Januganj, Balasore – 756019, Orissa, Fax No.-06782-263259  
**Regd. Office:** 123, Sec-A, Zone-A, Mancheswar Industrial Estate, Bhubaneswar-756010, Orissa

---

---

**No - 19144**

**Date-18.12.09**

**CORRIGENDUM TO TENDER NOITCE NO. 17475 DTD 27.11.09**

Due to Certain unavoidable circumstances the submission of Tender for tender Notice No. 17475 dtd 27.11.09 is here by extended and rescheduled as follows:

Sale of tender document (during office hrs. working days): **Extended upto 05.01.2010 upto 1 P.M**

* The last date and time of receipt of tenders:	<b>05. 01.2010 up to 5 PM</b>
* Date and time of opening of Technical Bids:	<b>06.01.2010 11 AM</b>
* Date and time of opening of Price Bids:	<b>06.01.2010 3 PM</b>

Also the following points of Section-II of the T.No .No 17475 dtd 27.11.09 stands modified as in below:-

**Point-1 (Scope of Work):-**

**Clause 1.**Complete replacement of coils (both HV & LV) which are found to be damaged by new coils & return of old damaged coils & return of old damaged coils to the Store. In this case the time period allowed will be 60 days for the date of receipt of burnt one from the Store.

**Clause 2.**Reinsulation of LV coil ( if found damaged) & replacement of HV winding .In this case ,the time period for the same will be 30 days from the date of receipt of burnt transformer from the store.

**(The rates should be quoted separately for the above two cases.)**

**Point-16 (Return of Old Materials):-**In case of work mentioned in the scope of work (1) ,all old materials e.g, burnt coils ( HV & LV Coils) ,LT & HT bushing Studs ,Bushing ( LT & HT) etc should be returned to the store. In case of work order as mentioned in the scope of work (2) there is no need of return of burnt coils. However Bushing Stud, Bushing (Both LT & HT) should be returned to the Store.

**All Other terms & Conditions remain unaltered.**

**Chief Executive Officer**  
**NESCO, Balasore**